TUG WebEx Meeting Notes March 20, 2024

Scott Marsh - Manager, Ops & Security

- YTD operations are up 2%. International arrivals are up 11% YTD.
- Busiest day Thursday Feb. 15, 578 movements
- Daily average 404 movements
- New TEB Control Tower will be commissioned in Fall 2024 (opening scheduled for Oct. 19)
- Runway 1/19 rehab project mill & pave, install LED lighting (June 2024)
- Stormwater drainage project multiple locations on airport, necessitating runway closures
 - June 6 to Sept. 1 Closures on Sundays 0000L to 1200L
- FAA construction
 - Convert Rwy 1 VASI to PAPI
 - Power distribution updates
- Reminder of 100,000 lb. aircraft weight limit at TEB.

Matthew Petersen - FAA, Acting KTEB ATCT Manager

- If Customs at Hangar 1 is closed, notify Tower on arrival that you'll be taxiing to Jet Aviation to clear Customs. Tower doesn't always know when Hangar 1 Customs is closed.
- SWAP Weather Events
 - o Don't file multiple flight plans. This causes confusion for ATC and flight crews.
 - If gate holds are in effect, make sure passengers are aboard and ready to go departure routes can open at a moment's notice.
 - o Low-level routes are often available notify ATC that you can accept these.
- Signature West / Meridian Merger
- Historically busy dates:
 - Spring Break departures last 2 weeks of March
 - o Easter March 31
 - Masters April 8-14
 - o Passover April 22-30
 - Kentucky Derby May 4
 - Mothers' Day May 12
 - College graduations May 11-19
 - Preakness May 18
 - Memorial Day May 27
 - Belmont Stakes June 8
 - Tony Awards June 16
 - US Open Golf in Pinehurst, NC June 13-16
 - Soccer at MetLife Stadium
 - June 25 @ 2030L Chile vs. Argentina
 - June 27 @ 2030L Uruguay vs. Bolivia
 - July 9 @ 1930L Semifinals

The 2026 World Cup final will be played at MetLife Stadium (near TEB) on July 19, 2026.
 Operations at TEB will likely increase substantially around that time.

Steve Chandoha -- General Manager, Signature Aviation Teterboro West Terminal,

https://www.signatureaviation.com/locations/TEB/west

- Signature West has merged with Meridian at TEB
- The ramp isn't very deep for parking. The current solution is lane lines painted on the parking area, each with lane identification numbers.
- After landing, pilots should contact the Signature West Ramp Coordinator, who will advise them which lane to park in. Follow-me carts and wing walkers will be used.
- When calling Ground for outbound taxi, pilots should advise controller which lane they're in.

Gabe Andino – Manager, Noise Abatement and Environmental Compliance

- TEB Good Neighbor Awards presented to operators in recognition of meeting noise goals and adhering to recommended operating hours
- When airport is on a north flow, pilots are encouraged to utilize a departure from Kilo intersection of Runway 1 (aircraft performance permitting)

Lisa Valladares – AIN Media Group, Director of Marketing & Client Services

- AIN's Corporate Aviation Leadership Summit (CALS) is an invitation-only meeting of senior-level corporate aviation department decision-makers from the most recognizable companies in North America.
- The next event (CALS East) is scheduled for July 15-17, 2024, in Newport Jersey City, NJ.
- Applications to attend can be submitted at https://connect.ainonline.com/cals-2024

Fred Calvert - Executive Jet Management, Director of Safety Assurance and Air Safety Investigation

- Presentation: "On Speed on Target Mining FOQA Data to Reduce the Risk of Landing Accidents and Runway Overruns"
- ICAO FOQA requirement aircraft over 27,000 kg (59,525 lbs) in commercial operations
- What do we do with FOQA data? SOPs & policies; Training; Aircraft; Airport
- Data validation don't believe the data without thorough analysis! Many sources of error FDR systems errors, program errors, bad or poor-quality data, weather conditions. Crew is the LAST place we look.
 - Examples Roaring Fork Visual @ KASE, River Visual 19 @ KDCA
- Long flares reduce available stopping distance and increase probability of wing-strikes in certain aircraft
- Over 14,000 landings were analyzed. High approach speed was the biggest issue.
- Average touchdown point was 1,502' from threshold. Longest was 4,193' on 11,000' runway
- The second-by-second decisions (last 50') to make a safe landing is something the FDC can't detect
- Worst-case scenario involves failure of deceleration devices, requiring emergency braking system

- Acceptable touchdown points:
 - o 6,000' (or more) runway available: 500' to 2,000' from threshold
 - Less than 6,000' runway available: 500' to 1,500' max from threshold
- Types of landings with multiple risk factors:
 - Landing beyond touchdown zone
 - Touchdown with airspeed more than 6 kts. above Vref
 - Less than 3,000' of remaning runway to stop the aircraft

Ron Gofron – Klatt Works, Director of Sales and Marketing, https://www.klattworks.com/

- Developed the Smoke Assured Vision Enhanced Display (SAVED), a high-resolution display module added to the Pilot's and Co-Pilot's Emergency Oxygen Masks to provide HUD feeds and symbology to the flight crew in the event of a smoke emergency in the cockpit.
- First FAA-approved STC received in April 2023 for B777
- Hoping to have STC for a business jet this year.
- Lithium-lon batteries account for the majority of smoke incidents (37%)
- There's a smoke incident once every 48 hours on average
- Klatt Works is the only supplier that provides an FAA-approved, in-mask solution
- SAVED is installed in both pilots' full-face oxygen masks. HUD data is sent to the binocular display screens inside the masks, allowing pilots to see HUD symbology.
- System requires a forward-facing camera on the nose of the aircraft, and a HUD computer.
- Product attaches easily inside the oxygen face mask. 1- or 2-day installation, ~\$150,000

Michael Fiscus – Secretary, Teterboro Airport Community Benefit Fund

- The 38th Annunal Scholarship Golf Classic will be held on May 20, 2024, at the Basking Ridge Country Club.
- More information can be found at https://veoci.com/v/p/form/xjtytx7bnjf3

Dave Belastock - President, TUG

- FlightSafety Foundation Summit April 30 to May 1
- Next TUG meeting June 19, 2024